

Texas Department of Public Safety Commercial Vehicle Enforcement



25 Most Common Commercial Violations Discovered During Roadside Inspections

10/25/2022

DPS CVE Training Unit

1



Texas Department of Public Safety

Commercial Vehicle Enforcement

Top 5 Most Common Violations

- 1 Oil and Grease Leak
- 2 Windshield Washing System
- 3 Tires Less Than 2/32 of An Inch
- 4 Inoperable ID Lamp
- 5 Brake Hose / Tubing Chafing and Kinking

10/25/202

DPS CVE Training Unit

2



Texas Department of Public Safety

Next 5 Most Common Violations

- 6 Brake out of Adjustment
- 7 Inoperable Turn Signal Lamp
- 8 Inoperable Side Marker Lamp
- 9 Defective / Inoperative Automatic Slack Adjusters
- 10 Defective ABS Malfunction Indicator Lamp for Trailer made after 3-1-98

10/25/2022

DPS CVE Training Unit

nit



Next 5 Most Common Violations

- 11 Inoperable / Obscured Stop Lamp(s)
- 12 No / Expired Commercial Motor Vehicle Inspection Certificate
- 13 Fire Extinguisher Violation
- 14 Fail to Maintain a CMV Subject to Your Control
- 15 Exhaust Leak Under Truck Cab or Sleeper

. . / . . /

DPS CVE Training Unit

4



Next 5 Most Common Violations

- 16 Inoperable License Plate Lamp
- 17 Tread / Sidewall Separation
- 18 Inoperable Clearance Lamp
- 19 Power Steering Violations
- 20 Inoperable Backup Lamp

10/25/202

DPS CVE Training Unit

5



Next 5 Most Common Violations

- 21 Inoperable Head Lamp(s)
- 22 Damaged Windshield
- 23 Brakes Out of Service 20 Percent or More
- 24 Brake Hose or Tubing Chafing and or Kinking Under Vehicle
- 25 Tire Flat

10/25/2022

DPS CVE Training Unit



26th Most Common Violation

 Truck Tractor Lower Rear Retroreflective Sheeting for a Vehicle Manufactured after July 1997.

10/25/2022

DPS CVE Training Unit

7



Texas Department of Public Safety

Commercial Vehicle Enforcement

Retroreflective Sheeting Rear of Truck Tractors

- FMVSS 571.108 S8.2.4
 - Element 1 Horizontal, alternating colors, fenders, mud flaps or the back of the cab
 - Element 2 Two pairs of white strips, to the right and left upper contours of the cab

•

10/25/202

DPS CVE Training Unit

8



Updated 7-21-10











